

General Environmental Incident Summary

Incident: 1832 **Date/Time Notice:** 12/11/2012 1647 **DEM Incident No:**

Responsible Party: Enbridge Pipelines (North Dakota) LLC

Date Incident: 12/11/2012 **Time Incident:** 1600 **Duration:**

County: Ward **Twp:** 155 **Rng:** 82 **Sec:** 18 **Qtr:** SE SE

Lat: 48.24714 **Long:** -101.26370 **Method:** Derived from TRS

Location Description: 2625 Railway Ave, Minot ND 58701

Submitted By: Valerie Lavik

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Ryan Stahler
2505 16th St SW
Minot, ND 58701

Distance Nearest Occupied Building: 1280 Feet

Type of Incident: vac truck fitting failure

Description of Released Contaminant: Crude oil

Volume Spilled: 20.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Fitting failed on a vac truck releasing approximately 15 to 20 gallons of crude oil.

Risk Evaluation:

None

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Contaminated soil will be removed and disposed of at an approved facility.

Action Taken or Planned:

Product was absorbed with pads and contaminated soil was removed with skid steer.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 12/11/2012 **Status:** Reviewed - No Action Required

Author: Roberts, Kris

Updated Volume:

Notes:

Received phone notification from Ryan Stahler, Compliance Coordinator. Release of 15-20 gallons of crude oil happened inside the containment dike of their south above ground storage tank. Vac truck valve leak was cause. Absorbent pads used to deal with liquid, and impacted soil inside the dike will be removed by skid steer loader. Roberts was at this location on 12-6-12 on another issue. Diking and procedures more than adequate to deal with this small release.